

Site AC6C: Granville

Date Assessed: 30/11/04

GPS Coordinates: N 44° 44' 49.02''  
W 65° 31' 38.82''

Crossing Status: Partial restriction

Road Crossing: Culvert  
(concrete/square), 1m

Crossing Condition: In some disrepair,  
eroding in places

Restriction Indicators:  
Difference in stream width  
Bank slumping  
Difference in water level  
Scour pool

**Downstream of Crossing**

Creek: 5m wide at crossing, some bank slumping. Opens into the Annapolis Basin

Land: Beach

**Upstream of Crossing**

Creek: 1m wide, small scour pool, some bank slumping

Land: Small salt marsh bordered by trees and residences.

Comments: While there is not a huge restriction to tidal flow, this crossing is in need of repair, at which time enlargement of the opening should be considered.




Figure 1. Upstream view of crossing



Figure 2. Upstream of crossing



Figure 3. Downstream view of crossing



Figure 4. Downstream of crossing




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

