

Site CBNS11C: Cove Road

Date Assessed: 11/07/02

GPS Coordinates: N 45° 22' 36.2''
W 63° 52' 20.9''

Crossing Status: Partial Restriction

Road Crossing: Culvert, corrugated.
0.9m opening

Crossing Condition: In poor condition

Restriction Indicators:
Bank slumping
Hanging culvert

Downstream of Crossing

Creek: Opens into Cobequid Bay just
downstream of crossing

Land: Marshland, beach

Upstream of Crossing

Creek: 2.6m wide

Land: Wooded area, small amount of marshland

Comments: This crossing is located at the end of cove road, leading to a residential driveway. The culvert needs to be replaced with a larger opening and lower to the creek bottom. Clean up of the site is needed as well including repairs made to the wooded support structures around the culvert. Assessment of the area at high tide would help determine how much tidal flow reaches the crossing.



Figure 1.



Figure 2.



Figure 3.



Figure 4.



Figure 5.




Figure 6:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04311-150