

**Site CBNS13B:** Carrs Brook

**Date Assessed:** 20/06/02

**GPS Coordinates:** N 45° 23' 14.6''  
W 63° 55' 55.4''

**Crossing Status:** Partial Restriction

**Road Crossing:** Bridge, wooden, 5.6m opening

**Crossing Condition:** In need of repair

**Restriction Indicators:**

Bank Slumping  
Slack water

### Downstream of Crossing

**Creek:** 2.1m wide

**Land:** Marshland, dyke along one side of creek channel

### Upstream of Crossing

**Creek:** 2.1m wide

**Land:** Wooded area, residential

**Comments:** This bridge needs to be at the very least repair. Replacement of the bridge with a larger opening may benefit the system. Dredging under the bridge may help return more natural tidal flow and fish passage. Assessment of this crossing at high tide may better determine the degree of restriction to tidal flow.



**Figure 1.**




**Figure 2.**



**Figure 3.**



**Figure 4.**



**Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04312-141