

**Site CBNS18B:** North River, Five Islands

**Date Assessed:** 20/06/02

**GPS Coordinates:** N 45° 24' 43.0''  
W 64° 4' 58.2''

**Crossing Status:** No Restriction

**Road Crossing:** Bridge, concrete, 33.5m opening

**Crossing Condition:** Intact. There is an old wooden structure in the bank underneath bridge.

**Restriction Indicators:** None

### Downstream of Crossing

**Creek:** 15.5m wide, smooth flow, some bank slumping

**Land:** Residential, wooded area, marshland

### Upstream of Crossing

**Creek:** 11.5m wide smooth flow, bank slumping

**Land:** Residential, wooded area

**Comments:** While this crossing is not posing as a large restriction to tidal flow, the old bridge structure still in place under the new bridge is slightly pinching the river channel. There is also a lot of rock debris around base of the bridge which could be dredged. Size of the opening should be maintained and remove old bridge structure underneath it.



**Figure 1.**




**Figure 2.**



**Figure 3.**



**Figure 4.**



**Figure 5:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04313-74