

Site CBNS19B: Harrington River

Date Assessed: 20/06/02

GPS Coordinates: N 45° 25' 3.3''
W 64° 6' 18.9''

Crossing Status: No Restriction

Road Crossing: Bridge, concrete, 30m opening

Crossing Condition: Intact, some wear

Restriction Indicators: None

Downstream of Crossing

Creek: 16m wide, smooth, angular flow, some slack water need one bridge support structures

Land: Residential, wooded area

Upstream of Crossing

Creek: 18m wide, smooth, angular flow, some slack water need one bridge support structures

Land: Residential, wooded area

Comments: While the bridge spans the width of the river channel the supports structures are fairly large within the channel. The river also appears to have limited flow through only two of these openings. Possible dredging of gravel/rock under the bridge could improve tidal flow through all three openings, however further assessment of this area would be necessary, especially during high tide.



Figure 1.



Figure 2.



Figure 3.



Figure 4.




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04313-72