

Site CBNS3B: Folly River

Date Assessed: 19/06/02

GPS Coordinates: N 45° 23' 53.3''
W 63° 31' 44.5''

Crossing Status: No Restriction

Road Crossing: Bridge, concrete, 35m wide

Crossing Condition: In need of some repairs. Sidewalk sections of bridge are crumbling and the railings are breaking and falling down.

Restriction Indicators: None

Downstream of Crossing

Creek: 30m wide, smooth, straight flow, with little bank slumping. Bridge supports are causing channel to move mostly through half of the opening.

Land: Dyked farmland, residential, salt marsh vegetation

Upstream of Crossing

Creek: 35m wide, smooth, straight flow with little bank slumping.

Land: Dyked farmland, residential, salt marsh vegetation

Comments: Repair bridge and maintaining the size of the opening.




Figure 1.



Figure 2.



Figure 3.



Figure 4.




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04306-121