

**Site CBSS12C:** Cobequid Trail**Date Assessed:** 07/02/02

**GPS Coordinates:** N 45° 20' 50.4''  
W 63° 24' 5.6''

**Crossing Status:** Partial restriction.

**Road Crossing:** Culvert, corrugated.

**Crossing Condition:** In poor condition, rusted out and pieces are missing.

**Restriction Indicators:**

Difference in stream width  
Difference in water level  
Bank slumping  
Scour pools

**Downstream of Crossing**

**Creek:** ~1.7m wide with smooth, straight flow. Opens into Bay


**Land:** Mudflats.

**Upstream of Crossing**


**Creek:** 1.3m wide with smooth, straight flow.

**Land:** Active agricultural land with some marshland present.

**Comments:** Rusting culvert is beginning to collapse and should be replaced with larger opening.



**Figure 1.**



**Figure 2:**  
*Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)*

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94001-71