

**Site CBSS7C:** Cobequid Trail

**Date Assessed:** 01/08/03

**GPS Coordinates:** N 45° 21' 43.0''  
W 63° 21' 58.0''

**Crossing Status:** Partial restriction.

**Road Crossing:** Culvert, cement, 2.4m wide

**Crossing Condition:** Structure is intact. Culvert located quite high up along the bank which could interfere with regular water passage. Rock banking around culvert on upstream side to prevent erosion.

**Restriction Indicators:**  
Difference in stream width  
Bank slumping  
Turbulent flow

#### Downstream of Crossing

**Creek:** 5.7m wide with smooth, angular flow.


**Land:** Active agricultural land use.

#### Upstream of Crossing

**Creek:** 7.5m wide with smooth, straight flow.

**Land:** Marshland.

**Comments:** Replace culvert such that it is located lower on the bank to allow for more regular water flow, which currently only passes through during and close to high tide.






**Figure 1.**



**Figure 2.**



**Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94001-20