

**Site SH2C:** Princeport

**Date Assessed:** 10/07/02

**GPS Coordinates:** N 45° 16' 35.3''  
W 63° 27' 32.8''

**Crossing Status:** Partial Restriction

**Road Crossing:** Culvert, corrugated,  
1.87m in width

**Crossing Condition:** Intact, large  
boulders and rocks along banks to  
prevent erosion

**Restriction Indicators:**  
Difference in stream width  
Difference in water level  
Bank slumping

#### **Downstream of Crossing**

**Creek:** 4.5m width, smooth straight  
flow, tidal flow reaching crossing at very  
high tides

**Land:** Wooded area and marshland

#### **Upstream of Crossing**

**Creek:** 2.5m width, smooth straight flow

**Land:** Wooded area, residential and some marshland

**Comments:** Consideration should be made to enlargement of opening  
when repair or replacement is necessary.





Figure 1




Figure 2



Figure 3



Figure 4



**Figure 5:**  
*Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)*

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94011-3