

**Site ST5C:** Little Hurd Brook

**Date Assessed:** 10/07/02

**GPS Coordinates:** N 45° 9' 47.3''  
W 63° 19' 53.8''

**Crossing Status:** No Restriction

**Road Crossing:** Culvert (square),  
cement, ~ 2.5m

**Crossing Condition:** Intact but  
cement is eroding. There are wooden  
planks placed around culvert to help  
prevent erosion.

**Restriction Indicators:** None

#### Downstream of Crossing

**Creek:** 3m wide, smooth, straight  
flow, with some slack water around  
culvert opening

**Land:** Wooded area, residential

#### Upstream of Crossing

**Creek:** 2m wide, smooth, straight flow, with some slack water around culvert opening

**Land:** Wooded area, residential

**Comments:** This crossing does not appear to be very tidal, or may be at the tidal edge of the system.  
Maintain size of opening.





Figure 1



Figure 2



**Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94015-96