

**Site TA1B:** North River

**Date Assessed:** 06/19/02

**GPS Coordinates:** N 45° 23' 14.2''  
W 63° 17' 07.2''

**Crossing Status:** No restriction.

**Road Crossing:** Railbridge, steel

**Crossing Condition:** Structure is intact.

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** Site not assessed.

**Land:** Farmland.

**Upstream of Crossing**

**Creek:** Site not assessed.

**Land:** Wooded area combined with small residential development.

**Comments:** Tidal influence does not seem to be an issue at this site and flow is not being restricted by this bridge.





Figure 1



Figure 2



Figure 3



**Figure 4:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04312-196