

Site CCCB 11B: Haycock Brook (River Hebert) Date Assessed: July 8, Aug. 27-8, Nov. 18, 2003

GPS Coordinates: N 45° 38' 08.5''  
W 64° 22' 18.6''

Crossing Status: No restriction.

Road Crossing: 18m long, one lane steel bridge with wood supports for banks.

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 18m wide creek with slightly turbulent flow.

Land: Agriculture (grazing cattle).

Upstream of Crossing

Creek: 18m wide creek with slightly turbulent flow and a small scour pool where a channel flows into the creek.

Land: Fallow farmland.

Comments: When repair or replacement is needed, maintain the size of the opening.





Figure 1. Downstream of non restrictive bridge.



Figure 2. Downstream view of creek from the road.



**Figure 3:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 95020-116