

Site CCCB 22B: East Apple River

Date Assessed: July 8, Aug. 27-8,
Nov. 18, 2003

GPS Coordinates: N 45° 28' 21''
W 64° 46' 08''

Crossing Status: No restriction.

Road Crossing: 45m long steel bridge.

Crossing Condition: Structure is intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 22m wide creek with smooth flow and no evidence of erosion.

Land: No apparent land use. Ducks Unlimited Impoundment along left bank.

Upstream of Crossing

Creek: 22m wide creek with smooth flow and no evidence of erosion.

Land: No apparent land use.

Comments: Maintain size of opening when repair or replacement is needed.




Figure 1. Upstream of bridge.



Figure 2:




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04309-10