

Site CCCB 23B: Apple River

Date Assessed: July 8, Aug. 27-8,
Nov. 18, 2003

GPS Coordinates: N 45° 27' 56.6''
W 64° 46' 59.2''

Crossing Status: Partial restriction

Road Crossing: 23m long concrete and wood bridge with a 4m wide support structure in the middle.

Crossing Condition: Structure is intact but appears to be old.

Restriction indicators:
Bank slumping
Turbulent water flow

Downstream of Crossing

Creek: Some turbulent and divergent flow due to the 4m wide wooden bridge support in the middle of the river channel

Land: One of the banks is lined with a wooden structure, possibly an old wharf. Large salt marsh and Duck's Unlimited impoundment.

Upstream of Crossing

Creek: Some turbulent and divergent flow due to the 4m wide wooden bridge support in the middle of the river.

Land: Salt marsh up to the elevation rise. No apparent use of the land.

Comments: Maintain opening width but remove or minimize in stream bridge support structure.



Figure 1. Downstream of the crossing with the large wooden structure on one of the banks and the large wooden support structure under the bridge.



Figure 2. Old wooden structure downstream of the bridge, possibly an old wharf. DU impoundment off to the right




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 95016-8