

Site CCCB 9B: Maccan River Tributary

Date Assessed: July 8, Aug. 27-8,
Nov. 18, 2003

GPS Coordinates: N 45° 45' 40.0''
W 64° 16' 29.1''

Crossing Status: No restriction.

Road Crossing: 4m long wood bridge.

Crossing Condition: Bridge structure intact but showing serious signs of decay, road surface cracked.

Restriction Indicators: None

Downstream of Crossing

Creek: Creek is 3m wide with some salt marsh species right on the banks. Tide probably reaches crossing only on extreme tides.

Land: Agriculture; left side of creek used by cattle, right side displays evidence of harvesting hay.

Upstream of Crossing

Creek: Creek is 3m wide with some salt marsh species right on the banks. Tide probably reaches crossing only on extreme tides.

Land: Wetland/woodland.

Comments: Some minor repair work such as strengthening the railings. Maintain the size of the opening if replacement is ever considered. Evaluate downstream habitat for possible obstruction.




Figure 1. Upstream of the crossing. There are cracks in the road, and the railing is tilting over.



Figure 2. Under the bridge from the downstream side of the crossing. There is fencing across the creek at the bridge. Very few salt vegetation species.




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 95014-20