

Site DC11B: Acacia Brook (Acacia Valley)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 34' 59.64''
W 65° 45' 17.4''

Crossing Status: No restriction

Road Crossing: Bridge (concrete/wood) with steel rail, 17m

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: 15m wide, rocky bottom, straight flow. Mouth of river is crossed by DC9B further downstream.

Land: Some marsh vegetation along edges of brook. Some cabins and a boat launch further downstream.

Upstream of Crossing

Creek: 15m wide, rocky bottom, straight flow.

Land: Mostly wooded.

Comments: Crossing is not restricting tidal flow or fish passage. Maintain size of opening.






Figure 1. Downstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)