

Site DC20C: Haight Brook

Date Assessed: 26/08/04

GPS Coordinates: N 44° 34' 46.32''
W 65° 56' 0.72''

Crossing Status: Partial Restriction

Road Crossing: Culvert
(wooden/square), 2.5m

Crossing Condition: In need of repairs

Restriction Indicators:

- Difference in water level
- Turbulent flow
- Difference in stream width
- Divergent channel
- Scour pool
- Bank slumping

Downstream of Crossing

Creek: 6m wide with large scour pool.
Channel has been diverted through a
seawall running parallel to the beach.

Land: Salt marsh, beach and seawall.

Upstream of Crossing

Creek: 4m wide with scour pool and bank slumping.

Land: Salt marsh.

Comments: Debris has built up around and on top of culvert and it is in disrepair. The opening should be enlarged to restore natural tidal flow and increase fish passage.





Figure 1. Downstream view of culvert



Figure 2. Upstream of crossing



Figure 3. Downstream of crossing showing scour pool to the left (east) of the crossing. Main channel flows out through the seawall.

