

**Site DC22A:** Henderson Brook

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 34' 35.7''  
W 65° 50' 56.88''

**Crossing Status:** Complete restriction

**Road Crossing:** Aboiteau (upstream end: concrete/square with two round openings)

**Crossing Condition:** Intact

**Restriction Indicators:**

- Difference in water level
- Aboiteau/tide gate
- Difference in stream width
- Turbulent flow
- Difference in vegetation
- Slack water
- Scour pool

**Downstream of Crossing**

**Creek:** Opens into bay.


**Land:** Beach.

**Upstream of Crossing**

**Creek:** 8m wide.

**Land:** Agricultural dykeland.

**Comments:** This land is currently being used for farming and cattle grazing therefore replacement of the aboiteau may not be possible. Should the land no longer be used for this purpose the aboiteau should be replaced with a culvert to restore natural flooding and fish passage. This crossing should be considered along with crossing DC21A since they are part of the same area of farmland.





**Figure 1.** Upstream view of crossing



**Figure 2.** Upstream of crossing

