

Site DC26B: Sissiboo River (Weymouth Harbour)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 26' 7.50''
W 66° 00' 6.66''

Crossing Status: No restriction

Road Crossing: Bridge (concrete), 150m

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: Large river approximately 100m wide, straight flow with some turbulent water (eddies) near base of support structures. There is an inlet on north side of the bridge, next to wharf.

Land: There is a harbour just downstream of bridge that extends into the river channel.

Upstream of Crossing

Creek: Large river approximately 100m wide, straight flow with some turbulent water (eddies) near base of support structures. There is an inlet on north side of the bridge.

Land: Some marsh vegetation bordered by forest and some residences on north side.

Comments: The bridge, while it does not completely span the width of the river it is a large structure and is not a restriction to tidal flow or fish passage, maintain size of opening.





Figure 1. Upstream view of crossing



Figure 2. Downstream of crossing showing harbour and wharf.



Figure 3. Upstream of crossing showing inlet with bordering residences.




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)