

Site DC29B: Issacs Lake Brook (Belliveaus Cove Wharf)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 23' 16.02''
W 66° 03' 40.68''

Crossing Status: No restriction

Road Crossing: Bridge (wooden), 3m

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: Opens into harbour, bank slumping, large boulders around base of crossing, turbulent flow with eddies.

Land: Harbour and jetty, some marsh vegetation.

Upstream of Crossing

Creek: Natural channel diverted to flow parallel to the road and through site DC30C. There is some bank slumping and turbulent flow with eddies.

Land: Route 1 residential area borders north side of stream. South side of crossing there is an information centre and parking lot area.

Comments: This brook appears to be diverted by the harbour and road to flow through the ditch area next to the main road on through to DC30C to the upstream area. This crossing however, does span almost the width of the ditch area and therefore not acting as a huge restriction.






Figure 1. Upstream view of crossing



Figure 2. Upstream of crossing there is a small area between road and parking lot (ditch) leading to DC30C



Figure 3. Downstream of crossing, harbour and jetty




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)