

**Site DC30C:** Issacs Lake Brook (Belliveaus Cove)

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 23' 13.26''  
W 66° 03' 40.62''

**Crossing Status:** No restriction

**Road Crossing:** 2 culverts (concrete/square), 1.8m each, with 1 round (corrugated) drainage culvert, 0.75m

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** 4m width, divergent from original path. Channel flows along the ditch of Route 1 upstream of crossing DC29B.


**Land:** Harbour

**Upstream of Crossing**

**Creek:** 3m width, scour pool

**Land:** Residential yard borders north side of stream, some marsh vegetation and trees border south side

**Comments:** This brook appears to be diverted by the harbour and road to flow through the ditch area next to the main road. This crossing however, does not pose a restriction.






**Figure 1.** Downstream view of crossing



**Figure 2.** Upstream of crossing



**Figure 3.** Looking towards the downstream side of crossing from DC29B.



**Figure 4:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)