

Site DC36B: Duffy Brook

Date Assessed: 26/08/04

GPS Coordinates: N 44° 15' 4.62''
W 66° 07' 44.22''

Crossing Status: No longer tidal

Road Crossing: Culvert (concrete) square open bottom, 3m

Crossing Condition: Intact

Restriction Indicators: N/A

Downstream of Crossing

Creek: 1m wide, straight flow

Land: Wooded, residential, dirt road next to crossing (perpendicular to main road) which has a bridge (DC37B)

Upstream of Crossing

Creek: 1m wide, straight flow

Land: Wooded and residential, walking bridge next to crossing

Comments: No marsh restoration potential due to downstream aboiteau. If aboiteau is replaced to allow tidal flow, reassess this crossing. Fish passage is still a factor however this does not appear to be a barrier.




Figure 1. Downstream view of crossing.

Figure 2. Upstream of crossing showing walking bridge




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)