

**Site DC37B:** Duffy Brook

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 15' 4.02''  
W 66° 07' 43.98''

**Crossing Status:** No longer tidal

**Road Crossing:** Bridge (wooden), 2.7m

**Crossing Condition:** Intact

**Restriction Indicators:** N/A

**Downstream of Crossing**

**Creek:** Branches off from main creek


**Land:** Wooded and residential.

**Upstream of Crossing**


**Creek:** Ditch area along main road

**Land:** Wooded and residential.

**Comments:** This crossing is along a dirt road off route 1 next to crossing DC36B. It not poses to restriction to flow and due to the downstream aboiteau is no longer tidal.



**Figure 1.** Upstream view of crossing



**Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**