

**Site DC38B:** Germain's Brook

**Date Assessed:** 26/08/04

**GPS Coordinates:** N 44° 14' 8.16"  
W 66° 08' 1.2"

**Crossing Status:** No restriction

**Road Crossing:** Bridge (wooden) with footbridge on upstream side, 3.5m

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** 2m wide, smooth, straight flow.

**Land:** Wooded and residential.

**Upstream of Crossing**

**Creek:** 2m wide, smooth straight flow. Footbridge next to crossing wider than bridge, no restriction from this. Drainage culvert next to bridge flowing into river.

**Land:** Wooded, residential.


**Comments:** No salt marsh restoration potential. Maintain the size of opening upon repair to ensure adequate fish passage. Downstream there is a maintained estuary which is reached by salt water on high tides.



**Figure 1.** Upstream of crossing



**Figure 2.** Upstream view of crossing showing foot bridge



**Figure 3:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)