

Site DC47B: Salmon River

Date Assessed: 26/08/04

GPS Coordinates: N 44° 03' 12.96''
W 66° 09' 41.88''

Crossing Status: No restriction

Road Crossing: Bridge (steel/concrete),
44m

Crossing Condition: In poor condition

Restriction Indicators: None

Downstream of Crossing

Creek: Large river (40m wide) with some bank slumping and erosion. The river branches off before it reaches the bridge, leading to DC48B.

Land: Salt marsh area on the north side of river where tributary branches off, old wharf area on the south side.

Upstream of Crossing

Creek: 40m wide straight flow

Land: Some marsh vegetation along edges of river, mostly wooded and residential.

Comments: Remnants of an old bridge just upstream should be removed, as it may be causing some disruption to flow. This river is experiencing some erosion possibly enhanced by crossing.






Figure 1. Downstream of bridge, old wharf and buildings at mouth of river



Figure 2. Downstream of bridge, north side of river showing tributary and salt marsh system



Figure 3. Upstream of crossing



Figure 4. View of bridge from road.




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)