

**Site N12C:** Lighthouse Lane

**Date Assessed:** 08/05/01

**GPS Coordinates:** N 45 18' 02.8''  
W 63 45' 09.0''

**Crossing Status:** Partial restriction

**Road Crossing:** Culvert (wooden box)

**Crossing Condition:** Intact, some debris in opening

**Restriction Indicators:**  
Scour pool  
Bank slumping

**Downstream of Crossing**

**Creek:** 2-3m wide, smooth, straight flow, slight bank slumping and small scour pool


**Land:** Salt marsh, encroaching development (cottages), road borders channel on one side

**Upstream of Crossing**

**Creek:** Smooth, traight flow, slight bank slumping and small scour pool forming

**Land:** Floodplain, possible grazing

**Comments:** Culver is in good repair and large in size for the system





**Figure 1**




**Figure2**



**Figure 3**



**Figure 4**



**Figure 5:**  
 Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04321-8