

Site N15B: Walton River

Date Assessed: 08/05/01

GPS Coordinates: N 45 13' 44.1''
W 64 00' 19.8''

Crossing Status: No restriction

Road Crossing: Bridge (concrete/steel)

Crossing Condition: Intact, woody debris

Restriction Indicators: None

Downstream of Crossing

Creek: >100m wide, straight flow, bank slumping, scour pool, slight divergent path

Land: Salt marsh, rocky beach, residential and business development

Upstream of Crossing

Creek: 100m wide, divergent channel, bank slumping

Land: Salt marsh, wooded, residential

Comments: The bridge opening is slightly smaller than the channel but appears to be sufficient for tidal exchange.





Figure 1. Upstream view of crossing



Figure 2. Upstream of crossing



Figure 3. Downstream view of crossing



Figure 4. Upstream of crossing




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04317-93