

Site N16C: Rainy Cove**Date Assessed:** 15/05/01

GPS Coordinates: N 45 13' 12.9''
W 64 04' 05.3''

Crossing Status: Complete restriction

Road Crossing: Culvert (concrete)

Crossing Condition: Intact

Restriction Indicators:

- Difference in water levels
- Turbulent flow
- Difference in stream width
- Slack water
- Difference in vegetation
- Scour pool

Downstream of Crossing

Creek: 30m wide, some slack water, turbulent flow and eddies in areas, scour pools.

Land: Salt marsh and beach. Remnants of old bridge restricting flow.

Upstream of Crossing

Creek: 10m wide, smooth flow, slack water

Land: Floodplain

Comments: Culvert should be lower to improve flow upstream. The downstream bridge should be removed if it is no longer in use.





Figure 1. Downstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Remnants of old bridge downstream of crossing causing some further restriction



Figure 4. Downstream of crossing



Figure 5. Upstream view of crossing

Figure 6. Upstream of crossing



Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04317-88