

**Site N1A:** Five Mile River

**Date Assessed:** 08/05/01

**GPS Coordinates:** N 44 15' 0.60''  
W 63 28' 10.8''

**Crossing Status:** Partial restriction

**Road Crossing:** Aboiteau  
Steel gate detached

**Crossing Condition:** In need of repair

**Restriction Indicators:**

- Difference in stream width
- Bank slumping
- Difference in water level
- Slack water
- Difference in vegetation
- Aboiteau/tide gate
- Scour pool
- Turbulent water

**Downstream of Crossing**

**Creek:** Opens into main channel


**Land:** Mudflats

**Upstream of Crossing**

**Creek:** Scour pool at mouth of crossing

**Land:** Old road bed, drainage area and swampland. Adjacent to Ducks Unlimited Impoundment.

**Comments:** Enlarge opening





**Figure 1.** Downstream view of crossing

**Figure 2.** Downstream of crossing




**Figure 3.** Downstream view of crossing

**Figure 4.** Downstream of crossing



**Figure 5.** Downstream of crossing





**Figure 6:**  
*Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations*

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94012-53