

**Site N20C:** Mill Brook

**Date Assessed:** 15/05/01

**GPS Coordinates:** N 45 10' 28.5''  
W 64 09' 48.3''

**Crossing Status:** Partial restriction

**Road Crossing:** Culvert (concrete)

**Crossing Condition:** Intact

**Restriction Indicators:**

- Difference in stream width
- Turbulent flow
- Difference in vegetation
- Slack water
- Scour pool

**Downstream of Crossing**

**Creek:** 10m wide, turbulent flow, eddies, scour pool

**Land:** Rocky beach

**Upstream of Crossing**

**Creek:** >10m wide, smooth flow, slack water and eddies in places, scour pool

**Land:** N/A

**Comments:**

**No Pictures Available**





**Figure 1: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04308-83