

Site N21C: Cheverie Creek

Date Assessed: 15/05/01

GPS Coordinates: N 45 09' 32.6''
W 64 10' 12.9''

Crossing Status: Partial restriction

Road Crossing: Culvert (wooden box)

Crossing Condition: In need of repair

Restriction Indicators:

- Difference in stream width
- Bank slumping
 - Difference in water level
- Slack water
 - Difference in vegetation
- Divergent channel
- Scour pool

Downstream of Crossing

Creek: Large scour pool causing a whirl pool at high tide, opens onto beach. Channel is divergent from original path, bank slumping

Land: Marsh, rocky beach and berm

Upstream of Crossing

Creek: 6m wide, large scour pool, bank slumping, divergent channel

Land: Salt marsh

Comments: Culvert should be replaced with a larger opening.





Figure 1. Upstream view of crossing



Figure 2. Upstream of crossing



Figure 3. Upstream scour pool



Figure 4. Downstream view of crossing



Figure 5. Downstream scour pool



Figure 6. Downstream of crossing

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04328-4