

Site N2A: Five Mile River

Date Assessed: 08/05/01

GPS Coordinates: N 45 15' 06.8"
W 63 28' 10.8"

Crossing Status: Complete restriction

Road Crossing: Aboiteau (cement/steel gate)

Crossing Condition: Intact

Restriction Indicators:

- Difference in stream width
- Bank slumping
- Difference in water levels
- Turbulent flow
- Difference in vegetation
- Slack water
- Scour pool
- Aboiteau/tide gate

Downstream of Crossing

Creek: >10m wide, turbulent flow, bank slumping and scour pool

Land: Floodplain


Upstream of Crossing

Creek: Smooth straight flow, bank slumping and scour pool.

Land: Non-use ditch area between road and upland; freshwater marsh

Comments: Assess the use of the land upstream and consider opening tide gate or replacing structure with a culvert.

No Pictures Available






Figure 1:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94012-52