

Site N3B: Maitland

Date Assessed: 08/05/01

GPS Coordinates: N 45 19' 03.4''
W 63 29' 49.9''

Crossing Status: Partial restriction

Road Crossing: Bridge (wooden)

Crossing Condition: In need of repair
(sides beginning to collapse)

Restriction Indicators:

- Difference in stream width
- Scour pool
- Bank slumping
- Turbulent flow

Downstream of Crossing

Creek: Turbulent flow, bank slumping and scour pool.

Land: Salt marsh, buildings border mouth of channel.

Upstream of Crossing

Creek: Smooth, straight flow, small scour pool and bank slumping.

Land: Salt marsh, residential.

Comments:



Figure 1. Downstream view of crossing





Figure 2. Downstream of crossing




Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 92334-63