

Site HCMB 11B: Kennetcook River (Hwy 215)

Date Assessed: 04/09/03,
05/12/03

GPS Coordinates: N 45° 01' 55.6''
W 64° 02' 02.4''

Crossing Status: No restriction

Road Crossing: 200m long concrete and steel bridge.

Crossing Condition:
Good condition, original design intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 180m wide with a straight, smooth flow.

Land: Dyked farmland on north side of the creek and cliff on the south side.

Upstream of Crossing

Creek: 180m wide with a straight, smooth flow.

Land: Dyked farmland on north side of the creek and cliff on the south side.

Comments: Bridge stretches bank to bank across river with two support structures within the river channel. When replacement/repair is needed, maintain the size of the opening. The dykelands along north side of river near crossing continue to be actively farmed, however small sections of dyked marshes upstream are no longer being farmed and there may be opportunities or salt marsh restoration.




Figure 1: View of the bridge from downstream standing on the dyke. The cliffs on the south side visible.




Figure 2: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



Figure 3: 2002 Aerial photograph containing tidal barrier data, (1: 10,000)