

**Site HCMB 22B:** Mt. Denison (Hwy 101)  
05/12/03

**Date Assessed:** 04/09/03,

**GPS Coordinates:** N 45 02' 56.9''  
W 64 10' 55.6''

**Crossing Status:** No restriction

**Road Crossing:** Steel and concrete bridge on Highway 101, Mt. Denison, crossing river and highway access road.

**Crossing Condition:** Intact

**Restriction Indicators:** None

**Downstream of Crossing**

**Creek:** Smooth flowing river which leads to crossings HCMB24B and HCMB23A, which is a tidal restriction.

**Land:** Woodland along one side of the river and agricultural land on the other (some dyking and ditching). Area occasionally experiences flooding.

**Upstream of Crossing**

**Creek:** Smooth flowing, non restricted creek.

**Land:** Flood plain and woodland.

**Comments:** This is part of the Highway 101 to be twinned. Expansion and/or new structures at this location should maintain opening size and the trend of minimal impact on rivers.






**Figure 1.** Photo taken from the road under the bridge.



**Figure 2.** Downstream of bridge.



**Figure 3: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)**

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 02327-111