

Site KCMB 11C: Lower Canard

Date Assessed: 04/09/03

GPS Coordinates: N 45° 08' 32''
W 64° 23' 33''

Crossing Status: No restriction.

Road Crossing: Steel culvert.

Crossing Condition: Culvert is in disrepair (bottom rotting out).

Restriction Indicators: None

Downstream of Crossing


Creek: 0.5m wide, smooth flowing creek.

Land: Tidal wetland.

Upstream of Crossing

Creek: 0.5m wide, smooth flowing creek.

Land: Small wetland and upland agriculture.



Comments: Roadway runs along upland edge of a tidal marsh and is primarily a drainage channel for upland area. A larger structure would improve hydrology but would not result in significant habitat benefits upstream or down. Crossing will need to be repaired or replaced in the near future.



Figure 1. Downstream view of the culvert with rotting bottom.




Figure 2:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



Figure 3: 2002
Aerial photograph
containing tidal
barrier data,
(1: 10,000)