

Site KCMB 3C: Creek off Gaspereau River

Date Assessed: 04/09/03, 05/12/03

GPS Coordinates: N 45° 05' 36.5''  
W 64° 16' 23.5''

Crossing Status: No restriction.

Road Crossing: 1.5m diameter steel culvert

Crossing Condition: Structure is intact.

Restriction Indicators: None

**Downstream of Crossing**

Creek: A small pool has formed in front of the culvert. There is a blockage of debris approximately 3m downstream.

Land: No apparent land use.

**Upstream of Crossing**

Creek: 1m wide creek with smooth flow.

Land: No apparent land use. Rise in elevation.

Comments: Clear away debris. When repair or replacement is necessary, maintain the size of the opening.






**Figure 1.** Downstream of creek.



**Figure 2.** Upstream of creek.



**Figure 3:** Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



**Figure 4:** 2002 Aerial photograph containing tidal barrier data, (1: 10,000)