

Site KCMB 4B: Wallbrook

Date Assessed: 04/09/03, 05/12/03

GPS Coordinates: N 45° 05' 05''
W 64° 18' 07''

Crossing Status: No restriction.

Road Crossing: 60m long concrete and steel bridge.

Crossing Condition: Intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 28m wide, smooth flow, with some bank slumping. The current channel appears divergent from original channel.

Land: Agricultural dykeland.

Upstream of Crossing

Creek: 28m wide, smooth flow, with some bank slumping. The current channel appears divergent from original channel.

Land: Agricultural dykeland.

Comments: Bridge spans the main river channel and creates very little obstruction to tidal flow. Adjacent lands are dyked and appear to be actively farmed. .






Figure 1. Full view of the bridge.




Figure 2: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)



Figure 3: 2002
Aerial photograph
containing tidal
barrier data,
(1: 10,000)