

Site KCMC22B: Harbourville

Date Assessed: 02/12/04

GPS Coordinates: N 45 09' 4.62''
W 64 48' 36.42''

Crossing Status: No restriction

Road Crossing: Bridge (wooden), 12m

Crossing Condition: Intact but showing wear

Restriction Indicators: None

Downstream of Crossing

Creek:

Land: Harbour, beach

Upstream of Crossing

Creek:

Land: Wooded, residential

Comments: This crossing does not restrict tidal flow or fish passage. When repair is necessary maintain the size of opening.





Figure 1. Upstream view of crossing



Figure 2. Upstream of crossing



Figure 3. Downstream view of crossing



Figure 4. Downstream of crossing




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 02308-41