

Site CCCB 24B: West Apple River

Date Assessed: July 8, Aug. 27-8,
Nov. 18, 2003

GPS Coordinates: N 45° 27' 56.1''
W 64° 49' 36.3''

Crossing Status: Partial restriction.

Road Crossing: 14m long wooden bridge with opening of 1.5m.

Crossing Condition: Structure appears old and beginning to show wear. Remnants of older crossing still in place underneath current bridge.

Restriction Indicators:
Difference in stream width
Structure failure

Downstream of Crossing

Creek: The creek is approximately 12m wide. Flow is pinched by the old structure under the bridge.

Land: Tidal creek, salt marsh, woodland and beach opening into bay

Upstream of Crossing

Creek: Pinched by remnants of old crossing

Land: Forest and salt marsh.

Comments: Remove the old structure to relieve pinching, repair bridge.




Figure 1. Downstream of the crossing. The old structure under the bridge is visible.



Figure 2. Upstream of the crossing approaching high tide.



Figure 3. Downstream of crossing approaching high tide.




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 95016-5