

Site CCCB 3B: LaPlanche River (Amherst Hwy 104)

Date Assessed: 01/08/03

GPS Coordinates: N 45° 49' 58.4''
W 64° 14' 18.6''

Crossing Status: No longer tidal.

Road Crossing: Two 30m long concrete bridges (divided highway).

Crossing Condition: Structures are intact.

Restriction Indicators: N/A

Downstream of Crossing


Creek: 10m wide.

Land: Actively being farmed.

Upstream of Crossing

Creek: 10m wide.

Land: Actively being farmed.



Comments: When repair or replacement is necessary, maintain the size of the opening. If obstructions downstream are removed, a new assessment of the crossing should be done. Evaluate land use and downstream obstructions for potential remediation or removal.



Figure 1. Downstream of the crossing is being actively farmed and is no longer tidal.



Figure 2. The bridge as seen from the upstream bank.

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 95002-16