

Site CCMC 28B: Spencer's Island

Date Assessed: July 8, Aug. 27-8,  
Nov. 18, 2003

GPS Coordinates: N 45° 21' 25.7''  
W 64° 42' 38.8''

Crossing Status: Partial restriction.

Road Crossing: 5.5m long wooden bridge.

Crossing Condition: Original structure is intact.

Restriction Indicators:  
Difference in stream width  
Bank Slumping  
Scour pool

**Downstream of Crossing**

Creek: Approximately twice as wide as the opening, with evidence of bank erosion and scour pool, but the flow is relatively smooth.

Land: Salt marsh, beach and campground

**Upstream of Crossing**

Creek: Approximately twice as wide as the opening, with evidence of bank erosion, but the flow is relatively smooth.

Land: Salt marsh.

Comments: Maintain or enlarge opening size when repairing or replacing. Enlarging this opening would increase tidal flow to upstream area and between and beyond this crossing and CCMC 28A and 29C (This crossing is seaward opening that provides tidal flow to the marsh area and creeks leading to CCMC 28A and 29C).





Figure 1. Upstream of the crossing with lots of salt marsh vegetation.




Figure 2: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04307-131