

Site AC10B: Moose River (West)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 39' 38.58''
W 65° 36' 15.54''

Crossing Status: No restriction

Road Crossing: Bridge (concrete), 5.7m opening

Crossing Condition: Intact but showing wear

Restriction Indicators: None

Downstream of Crossing

Creek: 5m wide tributary of Moose River, straight flow, turbulent, rocky bottom

Land: Moose River system, edge marsh and wooded

Upstream of Crossing

Creek: 4m wide, straight flow, turbulent, rocky bottom.

Land: Wooded and residential. Creek is bordered by residential yard.

Comments: There is little restriction to tidal flow or fish passage by this crossing.




Figure 1. Downstream view of crossing



Figure 2. Downstream of crossing



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

