

Site AC3C: Croscup Brook

Date Assessed: 30/11/04

GPS Coordinates: N 44° 42' 41.52''
W 65° 38' 1.26''

Crossing Status: Partial restriction

Road Crossing: Culvert (concrete),
1.5m, with overhanging smaller
corrugated culvert for drainage

Crossing Condition: Intact

Restriction Indicators:

- Difference in stream width
- Bank slumping
- Turbulent flow

Downstream of Crossing

Creek: 3m wide, bank slumping and
turbulent flow.

Land: Beach with some marsh
vegetation.

Upstream of Crossing

Creek: 1.5m wide, turbulent flow, bank slumping, trees falling in creek.

Land: Residential and wooded.

Comments: This crossing is not very tidally influenced due to the rise in elevation however it is slightly restricting water flow and stream width upstream.



Figure 1.
Downstream
view of crossing



Figure 2: Downstream of crossing



Figure 3. Upstream of crossing




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

