

Site AC7A: Annapolis River (Hydro dam)

Date Assessed: 26/08/04

GPS Coordinates: N 44° 45' 1.56''
W 65° 30' 42.9''

Crossing Status: Complete restriction

Road Crossing: Hydro dam

Crossing Condition: Intact

Restriction Indicators:
Difference in stream width
Turbulent flow
Difference in water levels
Tide gates

Downstream of Crossing

Creek: Opens into Basin

Land: Residential, forested and some marsh

Upstream of Crossing

Creek: Large river system

Land: Residential and forested

Comments: There is no potential for restoration because this is a functioning hydroelectric dam.




Figure 1. Upstream view of crossing



Figure 2. Downstream view of crossing.



Figure 3. Upstream of crossing, view of Annapolis River system.




Figure 4: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

