

Site **CBNS10B**: Little Bass River

Date Assessed: 20/06/02

GPS Coordinates: N 45° 23' 59.6''
W 63° 48' 26.6''

Crossing Status: No Restriction

Road Crossing: Bridge, wooden, 8.5m opening

Crossing Condition: Intact but showing wear

Restriction Indicators: None

Downstream of Crossing

Creek: 8.5m wide, smooth, straight flow with some bank slumping

Land: Marshland, residential

Upstream of Crossing

Creek: 8.5m wide, smooth, straight flow with some bank slumping. Channel may be diverted slightly due to the bridge structure.

Land: Marshland, residential, wooded area

Comments: The size of the bridge opening should at the very least be maintained as it just spans the width of the channel. However the bridge support structure in the middle of the creek is very large and while no posing as a huge barrier to tidal flow, the design could be reconsidered and replaced by a single opening when repairs or replacement is made.




Figure 1.



Figure 2.



Figure 3.



Figure 4.



Figure 5.




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04306- 97