

Site CBNS2B: Debert River

Date Assessed: 19/07/02

GPS Coordinates: N 45° 23' 43.3''
W 63° 30' 38.9''

Crossing Status: No Restriction

Road Crossing: Bridge, concrete, 27m wide

Crossing Condition: Intact.

Restriction Indicators: None

Downstream of Crossing

Creek: 14m wide, smooth, straight flow

Land: Wooded area, residential, some farmland

Upstream of Crossing

Creek: 12m wide, smooth, angular flow

Land: Wooded area, campground

Comments: Maintain size of bridge opening. There are dyking along sides of river and a dirt road on one side cutting off an area of land that should be salt marsh. There are also three old unused culverts near bridge covered by grasses and one filled in with cement. Sediment deposits (sand and gravel) are filling in the stream on one side of the bridge supports. Consideration should be made to whether dredging of this material would benefit tidal flow.






Figure 1. Upstream view of debris built up at site.



Figure 2



Figure 3



Figure 4




Figure 5: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 4306-123