

Site **CBNS5A**: Great Village River

Date Assessed: 25/06/02

GPS Coordinates: N 45° 24' 3.9''
W 63° 36' 23.6''

Crossing Status: Complete Restriction

Road Crossing: Aboiteau, 2 tide gates, cement, 4.5m openings

Crossing Condition: Intact and part of a maintain dyke

Restriction Indicators:

- Difference in stream width
- Divergent channel
- Difference in water level
- Tide gate/aboiteaux
- Bank slumping

Downstream of Crossing

Creek: 15m wide

Land: Marshland opening into Cobequid Bay

Upstream of Crossing

Creek: 13m wide

Land: Active farmland, wooded area, streamside marshland

Comments: Since this aboiteau is protective agricultural land removal of the tide gates may not be possible. Further assessment as to ability of fish to pass through crossing should be considered. While it may be possible for fish to pass, it is extremely limiting.





Figure 1.




Figure 2: Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04306-114