

Site CBNS6B: Portapique River

Date Assessed: 25/06/02

GPS Coordinates: N 45° 24' 23.2''
W 63° 42' 44.0''

Crossing Status: No Restriction

Road Crossing: Bridge, wooden, 44.4m wide

Crossing Condition: Intact

Restriction Indicators: None

Downstream of Crossing

Creek: 28m wide, smooth straight flow. There is a rock bank to prevent erosion and some full size trees fallen into middle of creek.

Land: Residential, wooded area

Upstream of Crossing

Creek: 30m wide, smooth, straight flow

Land: Residential, inactive dykeland, marshland

Comments: Maintain size of opening and remove debris from base of bridge.



Figure 1.



Figure 2.



Figure 3.



Figure 4.



Figure 5.




Figure 6:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 94007-33