

Site CBSS10C: Cobequid Trail,

Date Assessed: 07/02/02

GPS Coordinates: N 45° 21' 17.9''
W 63° 23' 6.0''

Crossing Status: Complete restriction.

Road Crossing: Culvert, corrugate,
~0.6m.

Crossing Condition: Structure is intact but half filled with mud. Tidal flow is only reaching at high tide and if it is not blocked by mud.

Restriction Indicators: N/A

Downstream of Crossing

Creek: Opens into Bay

Land: Mudflats


Upstream of Crossing

Creek: N/A

Land: Active agricultural use and wooded area.

Comments: Culvert needs to be replaced and lowered to allow for tidal flow.

* No Photos Available






Figure 1:
Property management and tidal barrier data for Nova Scotia (Service Nova Scotia, and Municipal Relations)

Air Photo Not Available in GIS Database

Access through Land Information Services:

Photo Number: 04316-76